


User manual

On/off

COB 100%-50%, XPE 100%-50%
Switch long push: strobe

Sensor button

Sensor on/off control the below modes
COB 100%, COB 50%, XPE 100%, COB 50%



Belt adjustable

Type C, charge

Sensor emission

 Sensor reception

Power display

Red- working
Red+Green –sensor working
Red-Battery charge
Green-Charge 100%

Made in china

140x160mm