
INSTRUCTION MANUAL

STANDING MIRROR WITH STORAGE K: 43331628 | T: 68747398



#	PARTS	QTY
A		2

#	PARTS	QTY
В		2

#	PARTS	QTY
С		4

#	PARTS	QTY
D		2
#	PARTS	QTY
Н		2

#	PARTS	QTY
E		1
#	PARTS	QTY
I		1

#	PARTS	QTY
F		1
#	PARTS	QTY
J		1

WARNING:

FRAGILE, HANDLE WITH CARE. ENSURE SECURE ATTACHMENT WHEN HANGING. PLEASE ENSURE CORRECT WEIGHT BEARING ARE USED WHEN HANGING THE MIRROR. FOR HANGING ADVICE CONSULT A DIY SPECIALIST BEFORE PROCEEDING.

PLEASE USE THE PRODUCT ACCORDING TO THE INSTRUCTIONS. MAXIMUM LOADING WEIGHT: 2KG

